



**Gold Bond
Building
Products**

A National Gypsum Division

37325

**CERTIFIED MAIL -
RETURN RECEIPT REQUESTED**

July 3, 1979

Ms. Beatrice S. Tylutki, Director
State of New Jersey
Dept. of Environmental Protection
Solid Waste Administration
P. O. Box 2807
Trenton, NJ 08625

Attention: Mr. Frank Coolick

Dear Ms. Tylutki:

Re: Former National Gypsum Co. Property
at Millington, New Jersey - Minor
Repairs Along Passaic River Bank

This is to confirm my phone conversation with Mr. Frank Coolick of your staff on July 2, 1979, on the above referenced subject.

Mr. William Bryant, our authorized Field Engineer, is presently at the site supervising the construction. He has been instructed to see that the above said repairs are performed in accordance with the approved plan, Permit No. 8419, 78-373 (Gold Bond Building Products drawings MJP 2 & 2a), and as field conditions warrant.

The exposed and/or loose material is removed in accordance with the above reference drawings, and rip rap is placed

Ms. Tylutki
July 3, 1979
Page 2

along the bank of the river. Toe wall is formed along the bank without affecting the width of the stream as much as possible.

If you have any questions, please advise.

Sincerely yours,



Padamshi Chheda
Structural Engineer

ec